To: Manzanilla, Enrique[Manzanilla.Enrique@epa.gov]; Allen, HarryL[Allen.HarryL@epa.gov]; Kao,

Jessica[Kao.Jessica@epa.gov]

Cc: Keener, Bill[Keener.Bill@epa.gov]

From: Zito, Kelly

**Sent:** Wed 8/12/2015 3:20:09 PM

Subject: URGENT: Gold King Mine Release - Situation Update 5
0810-0813 Operational Perid Gold King 207 ICS Org Chart.pdf
News Release 15-17 San Juan River Arm Caution .pdf

Gold King Situation Report 11Aug15.pdf

SanJuanRiverResponse SamplingLocations 150811.pdf

Gold King map Aug 11.pdf

Can you guys please help?

The R9 sit rep included here actually contains far less information than before.

It doesn't have a count of R9 staff/contractors (it says to see another attachment, which has a bunch of blanks in the org chart?), there's no cumulative/ongoing info on Montezuma creek water supplies, samples taken, monitoring sites, coordination with Navajo, etc.

There's also still no count on river miles from incident to Lake Powell, which Jared has been asking for... In addition, it all needs to be included in one document, not five.

I absolutely need to have more information – I am getting inundated with calls from the Administrator's office, the RA, the JIC, etc.

The only R9 information included is this:

## **EPA Region 9 Activities**

EPA Emergency response has established an Incident Command Post in Farmington, New Mexico, for field operations. EPA has deployed two OSCs and the START and ERRS contractor to assist with sampling and distribution of alternative drinking water respectively. Actions taken include:

- 1) Coordination of Ag/Livestock water needs,
- 2) Sampling for Surface Water and Sediment at the 11 locations on the San Juan River
- 3) Coordination with other Tribal, Federal, and State agencies.

Two additional OSCs will mobilize 8/12 to the ICP as additional sampling teams are deployed for surface water and sediment sampling. Boat operations are planned for these activities later in the week.

Current EPA Staffing: Please see attached ICS 207 organizational chart. We have expanded
operations of the regional REOC, having activated personnel to assist with Planning, Finance, and
Resources

From: Guria, Peter

Sent: Tuesday, August 11, 2015 6:27 PM

**To:** R9\_ER List; Ostrander, David; acrotty@navajo-nsn.org; jdelmar@navajo-nsn.org; Yogi, David; Hubbard, Secody; Lee, Bessie; hcleveland@navajo-nsn.org; Foster, Althea; Webster,

Susan; Hayes, Mark; Sandoval, Joni; Pease, Amanda

Cc: ebranch@nndoj.org; bidtahnbecker@navajo-nsn.gov; russellbegaye@gmail.com; jonmnez@yahoo.com; donbenn@navajo-nsn.gov; tflora@nndoj.org; Personal Email/Ex. 6 rjoe.opvp@gmail.com; rbegay@nndoj.org; dtaylor@nndoj.org; cbradley@nndoj.org; smpollack@nndoj.org; ronnieben@navajo-nsn.gov; nnepawq@frontiernet.net; ybarney@navajopublicwater.org; Johnson, AudreyL; Li, Corine; Montgomery, Michael; Cristiano, Gina; Farris, Laura; Lloyd, Lisa; Adams, Elizabeth; leslee.bechtel@azdema.gov Subject: Gold King Mine Release - Situation Update 5

Attached please find the SitRep, sampling location maps, and field operations organization chart for Region 9 Gold King Response activities for 10 August 15.

Pete Guria, Chief

Enforcement & Removal Operations Section

**USEPA** Region 9

415-972-3043

guria.peter@epa.gov